ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Brunat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
RR Nagara	16	Jalahalli
Street ID	**Street Name**	**Significant Landmark**
W0046	NA	Jalahalli
Unique Road No.	**Length of full Road(m)**	
16-W0046-93333	123.00	

Road Details

Road From	Road To
w0046	w0046
Type of Road	**Other Road Type**
Local	

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
0.00	4.00			compeleted
46.00	4.00			compeleted

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	Concrete		100.00	0.90	5	0.00	
	Concrete		100.00	0.90	5	0.00	compeleted

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	Concrete		100.00	0.90	5	0.00	compeleted

Received
ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂ
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 054

Drain

Particulars of side Drains

☐ Left

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered RCC Slabs		Others		Others

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.50

☐ Right

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered RCC Slabs		Others		Others

Other Flow Direction Type	Length (m)	Average Width(m)
	0.00	0.50

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
	0		

Existing Services

BESCOM	Yes	BWSSB	Yes
OFC	Yes	Manholes	Yes
Others			

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ರಾಜರಾಜೇಶ್ವರಿ ನಗರ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬೆಂಗಳೂರು-560 054

Inspection Details

Number of Trees 0

Date of Inspection 16/02/2016

Name umesh

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.